

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Chavez #1 location photo.

Stained soil around wet well head, noted in previous inspection report.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Well head is wet with oil. Area surrounding well head is stained.



Stained soil beneath load out valve on AST.