

Inspection Photos
Location Name: Moyer Unit 11-29
Location: 317535



Photo 1: Wellhead, currently TA.



Photo 2: Unused equipment on location.

Inspection Photos
Location Name: Moyer Unit 11-29
Location: 317535



Photo 3: Stained soil on location, around wellhead.