

Inspection Photos
Location Name: Moyer 'A'-612N56W
Locid#433344



Photo 1: Location

Photo 2: Wellhead

Inspection Photos
Location Name: Moyer 'A'-612N56W
Locid#433344



Photo from prior inspection for comparison



Photo 3: Stained soil removed, trash removed

Inspection Photos
Location Name: Moyer 'A'-612N56W
Locid#433344



Photo from prior inspection for comparison



Photo 4: Trash removed.

Inspection Photos
Location Name: Moyer 'A'-612N56W
Locid#433344



Photo from prior inspection for comparison



Photo 5: Stained soil, trash in separator house.

Inspection Photos
Location Name: Moyer 'A'-612N56W
Locid#433344



Photo 6: Stained soil at fitting



Photo 7: Stained soil at vessel

Inspection Photos
Location Name: Moyer 'A'-612N56W
Locid#433344



Photo 8: Stormwater erosion S of location.

