

Inspection Photos  
Location Name: Mallard 0780 1-15H22  
API: 05-057-06601



**Photo 1. Overview of location taken at entrance facing east.**

Inspection Photos  
Location Name: Mallard 0780 1-15H22  
API: 05-057-06601



**Photo 2. No wellhead sign.**



**Photo 3. Drilling and completions debris on location.**

Inspection Photos  
Location Name: Mallard 0780 1-15H22  
API: 05-057-06601



**Photo 4. Drilling and completions debris on location.**



**Photo 5. Debris blowing off location.**