



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing on flat areas, largely with grasses such as western wheatgrass (*Pascopyrum smithii*), intermediate wheatgrass (*Thinopyron intermedium*), and crested wheatgrass (*Agropyron cristatum*). Vegetation on cut-slope is sparse and needs monitoring and revegetation if cover is not increasing.



Photo 3. View of the eastern portion of the project area from the northeastern project area facing southward.



Photo 4. View of the northwestern portion of the project area, facing northward. What appears to be surface owner junk and debris is stored here and needs to be removed.



Photo 5. View of the southern portion of the project area from the southwestern edge facing eastward.

