

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2018

Submitted Date:

05/29/2018

Document Number:

677900441**FIELD INSPECTION FORM**

Loc ID 430382 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10460Name of Operator: HIGH PLAINS ENERGY LLCAddress: 4545 S MONACO STREET #116City: DENVER State: CO Zip: 80237**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Wheat, Randy	(720) 480-7776	rvwheat@comcast.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431414	WELL	SI	01/01/2015	OW	017-07727	PRONGHORN STATE 16-15-48 1-H	TA

**General Comment:**[Routine Inspection](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Gravel road through pasture off of county road			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Lease sign by gate at entrance			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Old fencing from around tank battery. Unused pipe, valves, electrical conduit, metal panels and old metal shed still on location			
Corrective Action:	Comply with Rule 603.f.			Date: 08/29/2018
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	LOCATION			
Comment:	Wire fence around entire location			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Vertical Separator	# 0			corrective date
Comment:	Removed from location			
Corrective Action:				Date:
Type: FWKO	# 0			
Comment:	Removed from location			
Corrective Action:				Date:
Type: Vertical Heater Treater	# 0			
Comment:	Removed from location			
Corrective Action:				Date:
Type: Ancillary equipment	# 0			
Comment:	Removed from location			

Corrective Action:		Date:	
Type: Flare	# 0		
Comment:	Removed from location		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Removed from location		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	400 BBLs	STEEL AST		38.736500,-102.778170
Comment:	Tank has been removed from location				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0	400 BBLs	STEEL AST		38.736500,-102.778170
Comment:	Tanks have been removed from location				
Corrective Action:			Date:		

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Berms need to be removed during the reclamation process			
Corrective Action:			Date:	

**Venting:**

Yes/No		
Comment:		

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 431414 Type: WELL API Number: 017-07727 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Well is TA at time of inspection. Passing MIT performed on 7/3/14. Passing MIT will be due on 7/3/19

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401655769	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4476606">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4476606</a>
677900446	Remove debris from location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4476605">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4476605</a>