

Inspected Facilities

Facility ID: 448950 Type: LAND API Number: - Status: Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)
Drill Cuttings	Land Application	Adequate	
Comment	COGCC followup inspection to Sandy Hill Land Application site. Cuttings and drilling fluid has been incorporated. Recent rain has generated overland flow of water and drilling mud with site soil. Berms on western edge of site have been breached, but stormwater and sediment was contained in the perimeter ditch. No additional offsite impacts were observed.		
Corrective Action	Inspection and maintain stormwater controls to prevent further degradation of controls and to prevent offsite impacts results from stormwater flow. Perform corrective actions by deadline or prior to next storm event.		Date: <u>06/05/2018</u>

Spill/Remediation:

Comment: [See photos of spill areas. Grass is growing through both spill areas.](#)

Corrective Action: [Submit status update via email or via Form 27 Supplemental for cleanup of Winick property.](#)

Date: 06/29/2018

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401655491	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4476406
679700926	Sandy Hill Site Photos 05-24-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4476403