

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2018

Submitted Date:

05/28/2018

Document Number:

688301879**FIELD INSPECTION FORM**Loc ID 322194 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	Field Ops Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209648	WELL	PR	11/01/2017	OW	039-06553	NORDMAN TRUST 41-20	PR

General Comment:Routine Inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	303-500-1160	Date:	
Corrective Action:			

Good Housekeeping:			
Type	OTHER		
Comment:	Gas engine leak (see attached photo). Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			
Crude Oil	WELLHEAD	<= 1 bbl			
Comment:	See attached photo. Inspector contacted pumper of 5/25/2018.				
Corrective Action:	Remove free fluids and contact COGCC EPS staff per Rule 906.b.				Date: 05/26/2018

In Containment: Yes

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	wire panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas engine, in shed		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	chemical container		

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	209648	Type:	WELL	API Number:	039-06553	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR. Feb 2018 production reported to COGCC database.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other				vegetation and strawbales
Berms	Pass					berms at wellhead
Rip Rap	Pass	Rip Rap	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401655019	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4475868
688301899	Petroshare Nordman Trust 41-20	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4475850