

Inspection Photos
Location Name: Javernick 1 DM
API: 05-043-40080
Inspection Number: 685200497



Wellhead and wedge valve with disconnected flowline segment and flowline riser



Wellhead with COGCC investigation sign installed, note circular area void of vegetation around well

Inspection Photos
Location Name:
API: 05-043-40080
Inspection Number:



Wellhead and around without vegetation, fence is approximate to Google parcel boundaries.

Inspection Photos

Location Name:

API: 05-043-40080

Inspection Number:



Flwline path going north

Flwline appears to be routed with irrigation system in places

Inspection Photos
Location Name:
API: 05-043-40080
Inspection Number:



Inadequate flowline marker as line goes north under RR tracks



Marker before roadway

Inspection Photos
Location Name:
API: 05-043-40080
Inspection Number:



Inadequate flowline marker as line goes through property and near home



Flowline path

Inspection Photos
Location Name:
API: 05-043-40080
Inspection Number:



Flowline path coming from south before going across Steinmeier to residence where gas was used in past.