

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401663891

Date Received:
06/05/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Schlagenhauf, Mark

mark.schlagenhauf@state.co.us

Roy, Catherine

catherine.roy@state.co.us

Fischer, Alex

alex.fischer@state.co.us

Beebe, Sabre

970-779-9398

Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800083

Inspection Date: 04/30/2018

FIR Submit Date: 05/01/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326369

Location Name: STATE GAS COM "CF"- Number: 16SWNW County: LA PLATA
N34N7W

Qtrqtr: SWN Sec: 16 Twp: 34N Range: 7W Meridian: N
W

Latitude: 37.216746 Longitude: -107.647084

FACILITY - API Number: 05-067- -00 Facility ID: 216321

Facility Name: STATE CF Number: 1

Qtrqtr: SWN Sec: 16 Twp: 34N Range: 7W Meridian: N
W

Latitude: 37.216746 Longitude: -107.647084

CORRECTIVE ACTIONS:

1 CA# 116170

Corrective Action:

Date: 06/01/2018

Operator shall "correct subsidence and reasonably minimize erosion" per Rule 1101.d (2) and "control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation." per Rule 1002.f(2).

Response: CA COMPLETED

Date of Completion: 05/31/2018

Operator Comment: Storm water BMP's have been installed on the pipeline and the well pad to prevent sediment travel. Silt traps and swells were installed on the top of the creek on the south side to prevent concentrated water flow cutting and washing into the creek. wattles installed to capture silt and slow down velocity of storm water. On the well pad diversion ditches were re-established and culvert inlet and outlet were cleaned out. See attached photos.

COGCC Decision: _____

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action addressed and photos attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 6/5/2018 4:00:20 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401663942	Work completed photos
-----------	-----------------------

Total Attach: 1 Files