

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2018

Submitted Date:

05/31/2018

Document Number:

688800136

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
320912 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: \_\_\_\_\_ 900 \_\_\_\_\_  
 Name of Operator: ALAMOSA DRILLING INC \_\_\_\_\_  
 Address: 8150 N. CENTRAL EXPY - STE 750 \_\_\_\_\_  
 City: \_\_\_\_\_ DALLAS \_\_\_\_\_ State: \_\_\_\_\_ TX \_\_\_\_\_ Zip: \_\_\_\_\_ 75205- \_\_\_\_\_

**Findings:**

- \_\_\_\_ 11 \_\_\_\_\_ Number of Comments  
 \_\_\_\_ 1 \_\_\_\_\_ Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296015	WELL	PR	09/26/2008	OW	007-06253	ALBERT MARTINEZ 1	EI

**General Comment:**

On May 29, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Alamosa Drilling Inc. Albert Martinez #1. For the most recent field inspection report for this facility, please refer to document #688800077. Corrective actions required by that document have not been addressed.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Free standing sign at tank battery.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	ASTs have NFPA placards and are labeled with contents and capacity.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Well head and surround soil are stained with oil.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Corrective action date taken from previous inspection.		Date: <u>05/21/2018</u>

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Hog wire enclosure around pump jack and well head.		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	
Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	HEATED STEEL AST		37.018616,-106.876683
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">Earthen berm secondary containment area shared with Nielson #4 300 bbl. crude oil AST.</a>					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No					
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 296015 Type: WELL API Number: 007-06253 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On May 29, 2018 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Alamosa Drilling Inc. Albert Martinez #1. For the most recent field inspection report for this facility, please refer to document #688800077. Corrective actions required by that document have not been addressed.</p> <p>During this inspection, stained soil was observed around the well head, as noted in previous inspection. The well head is wet with oil. Corrective action date has been taken from the last inspection to document days of non-compliance. Repair stuffing box leak, remove stained soil, and provide waste manifests for disposal of impacted material to COGCC EPS staff.</p>	hughesj	05/31/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401658775	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4479197">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4479197</a>
688800137	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4479196">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4479196</a>