

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2018

Submitted Date:

05/31/2018

Document Number:

689301234

FIELD INSPECTION FORM

Loc ID 334738 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Elsener, Garrett	(303)-565-4600	COGCC.inspections@caerusoilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261772	WELL	PR	11/03/2005	GW	045-07979	FEDERAL 10-1 (RA10)	PR
277640	WELL	PR	10/28/2005	GW	045-10737	FEDERAL 10-2D (RA10)	PR

General Comment:

[Routine Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:		
Comment:	1-800-791-7691	
Corrective Action:		Date:

Good Housekeeping:		
Type	WEEDS	
Comment:	Weeds next to the fence behind tank battery	
Corrective Action:	Comply with Rule 603.f .	Date: 06/10/2018

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:		
Type	LOCATION	
Comment:	Barbed wire fencing	
Corrective Action:		Date:

Equipment:		corrective date
Type: Plunger Lift	# 2	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Methanol tank
Other (Capacity)	500 gallon
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment: Holes in liner in battery containment				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).				Date: <u>07/01/2018</u>

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 261772 Type: WELL API Number: 045-07979 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Facility ID: 277640 Type: WELL API Number: 045-10737 Status: PR Insp. Status: PR

Producing Well

Comment: Well Producing on plunger lift

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Gradient Terraces						
Berms						
		Compaction				
Seeding						
Rip Rap						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401659182	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4480814
689301235	Inspection Photo 689301235	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4480810