

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2018

Submitted Date:

05/30/2018

Document Number:

689801160**FIELD INSPECTION FORM**

Loc ID 316751 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 9006Name of Operator: BOOCO'S CONTRACT SERVICES INCAddress: P O BOX 572City: HAYDEN State: CO Zip: 81639**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Booco, Randy		boocosinc@aol.com	owner operator
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232632	WELL	PR	09/01/2017	OW	107-06046	SMITH RANCHO 1-14	PR

General Comment:

Routine FIU inspection.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-276-3887

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Gravel stored on location.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD			
Comment:	Stained soil at wellhead. Absorbent pads present.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.			Date: 07/02/2018

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:		Date:		
Type: Pump Jack	# 1			
Comment:				
Corrective Action:		Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

CRUDE OIL	1	300 BBLs	STEEL AST		40.565000,-107.121230	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate			Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	232632	Type:	WELL	API Number:	107-06046	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pumping.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401659279	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4480902
689801170	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4480897