

Well Name : Jacques 2

API # : 067-06292



Photo 1: Wellhead sign previous inspection.



Photo 2: Wellhead sign.

Well Name : Jacques 2

API # : 067-06292



Photo 3: Unused riser with open ended pipe previous inspection.



Photo 4: Unused riser removed.



Well Name : Jacques 2

API # : 067-06292



Photo 5: Unused riser, fence post, and hose previous inspection.



Photo 6: Fence post and pipe.

Well Name : Jacques 2

API # : 067-06292



Photo 7: Disconnected pipe and knock out previous inspection.



Photo 8: Disconnected pipe, concrete blocks, and knock out.



Well Name : Jacques 2

API # : 067-06292



Photo 9: Tank and plastic spool previous inspection.



Photo 10: Tank and plastic spool.

Well Name : Jacques 2

API # : 067-06292



Photo 11: Conduit and wire.



Photo 12: Pipe and debris.



Well Name : Jacques 2

API # : 067-06292



Photo 13: Weed debris in pit fencing.



Photo 14: Metal flex hose outside tank fencing.

Well Name : Jacques 2

API # : 067-06292



Photo 15: Disconnected pipe inside tank fencing.



Photo 16: Smaller pipe and fittings inside pit fencing.



Well Name : Jacques 2

API # : 067-06292



Photo 17: Debris beside separator.



Photo 18: Wood debris inside sound walls.