

# Final Reclamation Inspection

June 11, 2018

Operator: HOMESTEAD OIL INC - #41050

API: 05-123-10108

Inspection Document #: 682403672

Weld County, CO

CNW Section 15 T4N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STATLER #1  
API: 05-123-10108



Google Earth aerial imagery taken August 18, 2012 of the battery location used for the three nearby Homestead wells during active operations.

Inspection Photos  
Location Name: STATLER #1  
API: 05-123-10108



Google Earth aerial imagery taken June 19, 2014 post plugging operations. On June 11, 2018, Staff observed subsidence where a former tank was and a DCP receiver remains at the location.



Inspection Photos  
Location Name: STATLER #1  
API: 05-123-10108



**Photo 1.** Photo taken from the northern battery location. A DCP receiver remains at the location. Operator shall remove all equipment per Rule 1004.a.



Inspection Photos  
Location Name: STATLER #1  
API: 05-123-10108



**Photo 2.** Photo taken from the southern battery location. Subsidence was observed where a former tank was located. There shall be no significant unrestored subsidence per Rule 1004.c.(1).





**Photo 3.** Photo taken from the approximate well location, facing West. Well location appears reflective of reference area crop levels.



Inspection Photos  
Location Name: STATLER #1  
API: 05-123-10108



**Photo 4.** Photo taken from the approximate well location, facing North. See comments under Photo 3.



Inspection Photos  
Location Name: STATLER #1  
API: 05-123-10108



**Photo 5.** Photo taken from the approximate well location, facing East. See comments under Photo 3.





**Photo 6.** Photo taken from the approximate well location, facing South. See comments under Photo 3.



Inspection Photos  
Location Name: STATLER #1  
API: 05-123-10108



**Photo 7.** Photo taken along a portion of the access road, facing West. See comments under Photo 3.





**Photo 8.** Reference photo taken west of the well and access road, facing West. Well location and access road appear reflective of reference area crop levels.