

Inspection Photos
Location Name: Lilli Unit #16-1
Location ID: 326966



Photo 1: Wellhead

Photo 2: Location

Inspection Photos
Location Name: Lilli Unit #16-1
Location ID: 326966



Photo from prior inspection for comparison



Photo 3: Stained soil at exhaust

Inspection Photos
Location Name: Lilli Unit #16-1
Location ID: 326966



Photo from prior inspection for comparison



Photo 4: Stained soil at engine

Inspection Photos
Location Name: Lilli Unit #16-1
Location ID: 326966



Photo from prior inspection for comparison



Photo 5: Stained soil at wellhead