

Inspection Photos
Location Name: Lilli Unit #10-2
Location ID: 326778



Photo 1: Location



Photo 2: Wellhead

Inspection Photos
Location Name: Lilli Unit #10-2
Location ID: 326778



Photo from prior inspection for comparison



Photo 3: No contents, capacity, NFPA labeling for concrete vault.

Inspection Photos
Location Name: Lilli Unit #10-2
Location ID: 326778



Photo 4: Weeds in tank battery