

FORM
INSPRev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2018

Submitted Date:

06/13/2018

Document Number:

679100194

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☒
KUBECZKO, DAVE 2A Doc Num: 401611002

Operator Information:

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Nolan Redmond		Inspections@catamountep.com	
Nolan Redmond	720-484-2347	nredmond@catamountep.com	
Dave Kubeczko		dave.kubeczko@state.co.us	

General Comment:

CATAMOUNT ENERGY PARTNERS LLC # 10464

Nolan Redmond 720-484-2347 nredmond@catamountep.com

Nolan Redmond Inspections@catamountep.com

Date of Inspection: 06-05-18

Type of Inspection: Form 2A, Fed / Fed, New Location

Location Name: Bull Creek Unit M34N5W-28NENW Pad; EBC #3, EBC #5, EBC #7 wells

Location ID #: TBD

Location: Archuleta County; NENW, Sec 28, T34N, R5W

Form 2A# 401611002

API #: TBD

Conducted onsite for proposed well pad location (total proposed disturbed area is 1.51 acres; approximate pad dimensions are 260' by 205') on 06-05-18; location will have a gravel pad, three wellheads, three separators, two tanks; location is ponderosa pine forest, sage brush, and grassland and will require interim reclamation after well completions and wells are in production; location should be inspected once constructed, drilled, completed, flowline tested, and in production. Location does not fall within SWH or RSO areas, however, operator has agreed to CPW and Forest Service wildlife recommendations including existing FS and BLM stipulations and COAs. Location is relatively flat, with gentle slopes to the southeast, therefore, the potential for erosion during construction and drilling/completion activities is low to moderate. Location is not in a "sensitive area".