



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern edge facing southward. Poor revegetation and rilling observed in the northeastern interim reclamation area. This needs to be monitored and stormwater controls installed if erosion worsens, and re-seeding if revegetation is not increasing.



Photo 3. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 4. View of musk thistles (*Carduus nutans*) within the project area.