

# *Inspection Photos*

*API#081-07364*

*Operator: Tatonka O&G*

*Inspection Number: 6741* 

*Inspection Date: 5/24/2018*





Photo#1:  
Overview of Location from Entry to Southeast.

May 24, 2018



Photo#2:  
Top of what was Cut slope at West side of Location looking South

May 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Tatonka Culverwell API#081-07364



Photo#3:  
View to Northwest .

May 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Tatonka Culverwell API#081-07364



Photo#4:  
View from center of Location to Southwest.

May 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Tatonka Culverwell API#081-07364



Photo#5:

View from center of Location to Northwest.

May 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Tatonka Culverwell API#081-07364



Photo#6:  
View Northwest to Entry.

May 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Tatonka Culverwell API#081-07364



Photo#7:

View from North side of Location to South. Dark green vegetation mounds are Scotch thistle.

May 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Tatonka Culverwell API#081-07364



Photo#8:  
Scotch thistle on Location.

May 24, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Tatonka Culverwell API#081-07364