

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2018

Submitted Date:

06/11/2018

Document Number:

689301268

FIELD INSPECTION FORM

Loc ID 432265 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
14 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Elsener, Garrett	(303)-565-4600	COGCC.inspections@caerusoilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432268	WELL	SI	08/01/2017	GW	045-21936	HMU 6-15A (J6SEB)	SI
432269	WELL	PR	05/20/2014	GW	045-21937	HMU 6-13AA (J6SEB)	PR
432272	WELL	PR	05/16/2014	GW	045-21938	HMU 6-11A (J6SEB)	PR
432277	WELL	PR	05/17/2014	GW	045-21939	HMU 6-12D (J6SEB)	PR
432280	WELL	PR	05/27/2014	GW	045-21940	HMU 6-15AA (J6SEB)	PR
432281	WELL	PR	05/14/2014	GW	045-21941	HMU 6-13A (J6SEB)	PR
432282	WELL	PR	05/17/2014	GW	045-21942	HMU 6-12DD (J6SEB)	PR
432283	WELL	PR	05/12/2014	GW	045-21943	HMU 6-13D (J6SEB)	PR
432284	WELL	SI	08/01/2017	GW	045-21944	HMU 6-15D (J6SEB)	SI

General Comment:
[Routine Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:	
Comment:	1-800-791-7691
Corrective Action:	
	Date:

Good Housekeeping:			
Type	OTHER		
Comment:	Stained Rock in Tank Battery containment, see photo		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.		Date: 07/11/2018
Type	WEEDS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		

Comment: Chemical units at Wellheads		Date:
Corrective Action:		Date:
Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 9	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 9	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLs	STEEL AST		
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	Methanol Tank
Other (Capacity)	1000 Gallon
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities										
Facility ID:	432268	Type:	WELL	API Number:	045-21936	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:		<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: EQUIPMENT ONSITE						
Comment:		Plunger Lift, Well S/I at time of inspection								
Corrective Action:								Date:		
Facility ID:	432269	Type:	WELL	API Number:	045-21937	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:		Well Producing on plunger lift								
Corrective Action:								Date:		
Facility ID:	432272	Type:	WELL	API Number:	045-21938	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:		Well Producing on plunger lift								
Corrective Action:								Date:		
Facility ID:	432277	Type:	WELL	API Number:	045-21939	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:		Well Producing on plunger lift								
Corrective Action:								Date:		
Facility ID:	432280	Type:	WELL	API Number:	045-21940	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:		Well Producing on plunger lift								
Corrective Action:								Date:		
Facility ID:	432281	Type:	WELL	API Number:	045-21941	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:		Well Producing on plunger lift								
Corrective Action:								Date:		
Facility ID:	432282	Type:	WELL	API Number:	045-21942	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:		Well Producing on plunger lift								
Corrective Action:								Date:		
Facility ID:	432283	Type:	WELL	API Number:	045-21943	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:		Well Producing on plunger lift								
Corrective Action:								Date:		

Producing Well

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

Facility ID: 432284 Type: WELL API Number: 045-21944 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: [Plunger Lift, WELL S/I in at time of inspection.](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Gravel				
Rip Rap						
Berms						
				Material Handling And Spill Prevention		
Hydro Mulch						
		Compaction				
Retention Ponds						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401669914	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4491112
689301269	Inspection Photo 689301269	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4491106