

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2018

Submitted Date:

06/18/2018

Document Number:

690100565**FIELD INSPECTION FORM**Loc ID 333124 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 42640Name of Operator: HYNDREX RESOURCESAddress: 1531 4TH AVECity: GREELEY State: CO Zip: 80631-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Whittington, Ellice		ellice.whittington@state.co.us	
Lara-Mesa, Susana		cogcc@kpk.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Berger, James	(970) 336-8830	jamesberger2@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240925	WELL	PR	07/01/2017	OW	123-08713	NESSSU-KINDER 16	EG

**General Comment:**

Flowline pressure testing observed (Off Location/ Post Repair). Photo's uploaded.

**Inspected Facilities**

Facility ID: 240925 Type: WELL API Number: 123-08713 Status: PR Insp. Status: EG

**Flowline**

#1	Type: Non-Well Site	1 of Lines	
----	---------------------	------------	--

Flowline Description

Flowline Type: Non-Well Site Size: 3" Material: Fiberglass  
 Variance: No Age: 20+ Yrs Contents: Multiphase

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Off location flowline pressure tested; Test was run and charted for approximately 48 hrs. The test recorded minimal pressure deviation (loss < 10%) and adequate stabilization. This test observed is deemed passing/ satisfactory. A data logger (Crystal Gauge) was used to record the pressure test (chart has been uploaded to this FIR).

Corrective Action: Date:

**COGCC Comments**

Comment	User	Date
Flowline system compromised via line strike on 5/25/18 by Noble Midstream during installation of 10" crude oil gathering pipeline. The flowline was repaired at 40.123391, -104.799772 on 5/30/2018 (Spill/ Release point ID #455229). Note: The NESSU 16 flowline was not directly compromised by the 3rd party line strike; however, tie's into the gathering system and was pressured tested as part of the overall integrity verification of this flowline system as a whole.	maclarej	06/18/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100595	NESSU #16 Flowline Pressure Test Chart	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4497394">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4497394</a>
690100596	Wellhead sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4497395">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4497395</a>
690100597	Crystal gauge (pressure display)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4497396">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4497396</a>