

# Inspection Photos

06/15/2018

Operator: FOUNDATION ENERGY  
MANAGEMENT LLC - 10112

Location ID: 331849

Inspection Doc. Number: 682503493  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 331849



**Photo 1:** Photo taken from the well location, facing west. Photo shows access road has not been reclaimed.



**Photo 2:** Photo taken from the south end of the well location. Photo of Diffuse Knapweed (lighter green plant in photo, red arrow) found on location.



Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 331849



**Photo 3:** Photo taken from the south end of the well location, facing northwest. Photo shows well location remains bare and exposed soil, or predominantly undesirable weedy plant species



**Photo 4:** Photo taken from the south end of the well location, facing northeast. Photo shows well location remains bare and exposed soil, or predominantly undesirable weedy plant species



Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 331849



**Photo 5:** Photo taken from the north end of the well location, facing south. Photo shows portion of the access road “loop” that remains evident.



**Photo 6:** Photo taken from the north end of the well location, facing west. Photo shows portion of the access road “loop” that remains evident.



Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 331849



**Photo 7:** Photo taken from the west of the well, facing south. Photo shows areas of the location where reclamation activities do not appear to have been conducted.



**Photo 8:** Photo taken from the well location, facing west. Photo shows access road has not been reclaimed. Photo also shows Field Bindweed along access road.



Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 331849



**Photo 9:** 2013 Aerial imagery. Photo shows areas (red polygon) where Noxious Weeds (Diffuse Knapweed) were observed on location and access road, and mapped using a GPS.

Inspection Photos  
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112  
Location ID: 331849

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	ACTION REQUIRED	Noticed diffuse knapweed (List B noxious weed) growing throughout the location/production facility which has developed seed heads.	Remove and control noxious weeds growing on the location/production facility. The noxious weeds need to be removed and properly disposed of to prevent the spread of the developed seed heads.	09/02/2015
STORAGE OF SUPL	ACTION REQUIRED	There is unused equipment being stored at the production facility. Noticed metal pipe,	Remove unused equipment and maintain the location in a workman like manner.	09/18/2015

**Photo 10:** A clip from Inspection #673502680 dated 8/17/2015 documenting Diffuse Knapweed concerns and requiring management.

**Inspection Photos**  
**Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112**  
**Location ID: 331849**

Inspector Name: Binschus, Chris

Corrective Action:

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	ACTION REQUIRED	Tank battery location was mowed within 2 days prior to this inspection; however, mowing by itself is not a sufficient control for mature Diffuse knapweed during this time of year. Mature Diffuse knapweed individuals were observed along the perimeter of the mowing area. Knapweed seed heads were observed in the mowed cutting areas. Refer to attached photos in Document #682401241.	Operator instructed on 8/25/16 to pull and bag remaining plants in areas that were not mowed. Operator instructed on 8/30/16 to collect, remove, and dispose weed debris and seed heads properly from areas that were mowed. Also, on 8/30/16, the 2-week corrective action date was set to perform the corrective actions.	09/13/2016

**Spills:**

**Photo 11:** A clip from Inspection #682401240 dated 8/25/2016 documenting Diffuse Knapweed concerns and requiring management.