

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2018

Submitted Date:

06/11/2018

Document Number:

685304851

FIELD INSPECTION FORM

Loc ID 428734 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 7650
Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION
Address: 4900 COLLEGE BLVD
City: FARMINGTON State: NM Zip: 87402

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|----------------|----------------------------|---------|
| Stradling, Zak | (505) 324-5074 | zstradling@bmgdrilling.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 214688 | WELL | PR | 05/30/2003 | GW | 067-06292 | JACQUES 2 | PR |

General Comment:

Inspection completed as follow up inspection requirement.
This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.
See link at end of report for path to downloadable pictures.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | DEBRIS | | |
| Comment: | Debris inside sound walls. Disconnected parts, wooden stakes, pipe, plastic spool, plastic tanks, and other production related debris. Corrective action not completed. Corrective action date remains the same to document days of noncompliance. | | |
| Corrective Action: | Remove debris to comply with Rule 603.f. | Date: | 11/23/2017 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Identified (1) unused riser. Removed/abandoned corrective action completed. | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 214688 Type: WELL API Number: 067-06292 Status: PR Insp. Status: PR

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401670283 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4491458 |
| 685304866 | Inspection photos. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4491456 |