

Inspection Photos
Location Name: Ptasynski 1X
API: 05-081-06614



Photo 1. Overview of location taken at entrance facing southwest.

Inspection Photos
Location Name: Ptasynski 1X
API: 05-081-06614



Photo 2. Stained soil at vertical separator.



Photo 3. Fresh gravel at wellhead.

Inspection Photos
Location Name: Ptasynski 1X
API: 05-081-06614



Photo 4. Only one tank labeled.



Photo 5. Stained soil at tank loadout.

Inspection Photos
Location Name: Ptasynski 1X
API: 05-081-06614



Photo 6. Pit with weeds and poor fencing.



Photo 7. Land farm area.