

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2018

Submitted Date:

06/07/2018

Document Number:

689801270**FIELD INSPECTION FORM**

Loc ID 312863 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Evans, Clay		antlerenergy@yahoo.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222661	WELL	PR	06/01/2015	GW	081-06021	FEDERAL-CHAMBERLIN 22-1	PR

**General Comment:**

Routine FIU inspection.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Some stained soil has been removed, smaller amounts remain. Dried vegetation has been cleared from immediate wellhead area.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:	Less than 50 feet from heated crude oil tanks. 40.90355, -108.28435		
Corrective Action:	Move equipment to comply with minimum 50 foot setback as per Rule 605.a.6.		Date: 02/27/2015
Type: Horizontal Heated Separator	# 1		
Comment:	Less than 50 feet from heated crude oil tanks. 40.90355, -108.28435		
Corrective Action:	Move equipment to comply with minimum 50 foot setback as per Rule 605.a.6.		Date: 02/27/2015
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	400 BBLs	HEATED STEEL AST		40.900390,-108.284260	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate			Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	222661	Type:	WELL	API Number:	081-06021	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pumping. Produced volumes are required to be reported accurately from the wellhead meter every month, and the form 7 reporting does not reflect that accurate measurement.								
Corrective Action:	Please contact Teri Ikenouye (production supervisor) to discuss reporting parameters.							Date:	07/19/2018

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)		
Oily Soil	Land Treatment	Inadequate	40.900060	-108.284380	
Comment	Landfarm mentioned in previous inspection. Not fenced. Fresh contaminated soil was observed in landfarm area during this inspection.				
Corrective Action				Date:	

**Spill/Remediation:**

Comment:			
Corrective Action:		Date:	

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801275	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4498704">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4498704</a>