

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2018

Submitted Date:

06/19/2018

Document Number:

689801272**FIELD INSPECTION FORM**Loc ID 313000 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments7 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Ikenouye, Teri		teri.ikenouye@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Evans, Clay		antlerenergy@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223250	WELL	PR	09/22/1985	OW	081-06614	PTASYNSKI 1X	PR

**General Comment:**

Routine FIU follow up inspection.

## Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers. Only one of two tanks labeled.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/27/2017

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	40.91554, -108.32214		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	40.91533, -108.32238 ~ 18 feet between pumpjack and heated separator.		
Corrective Action:	Move equipment to comply with minimum 75 foot setback as per Rule 605.b.(4).	Date:	01/14/2016
Type: Dehydrator	# 1		
Comment:	40.91554, -108.32214		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	#		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:	40.91535, -108.32202 Stained soil around separator base.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 07/19/2018

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	400 BBLS	HEATED STEEL AST		40.915110,-108.322270	
Comment:	Stained soil at tank loadout.					
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.					Date: 07/28/2016

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	223250	Type:	WELL	API Number:	081-06614	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Pumping. Produced volumes are required to be reported accurately from the wellhead meter every month, and the form 7 reporting does not reflect that accurate measurement.								
Corrective Action:	Please contact Teri Ikenouye (production supervisor) to discuss reporting parameters.							Date:	07/19/2018

**Environmental****Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)		
Oily Soil	Land Treatment	Inadequate	40.915120	-108.322340	
Comment					
Corrective Action	A previous operator opened a land treatment E&P facility in 2011. The facility was approved in Remediation project number 7362. No project updates have been received by COGCC since this project was started. By 5/28/2018, please provide a supplement eForm 27 update on project number 7362.				Date: <u>06/22/2018</u>

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): Comment: Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: Pit mentioned in previous reports.

Corrective Action

Date: 05/28/2018

The COGCC database shows 1 pit related with this well, 100408. It appears that the pit was closed between 2011 and 2014. By 5/28/2018, please provide documentation that the pit was closed per rule 905.

**COGCC Comments**

Comment	User	Date
<u>Follow up to inspection from 3/26/2017 document number 673404307. No corrective actions have been met.</u>	waldrone	06/19/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
689801277	Inspection Photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4498706">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4498706</a>