

McPherson A
Inspection # 689301178

Before:



Erosion along West side of access road

After:



Bar Ditch re-defined, rock check dams installed

McPherson A
Inspection # 689301178

Before:



Erosion along West side of access road

After:



Bar Ditch re-defined, rock check dams installed

McPherson A
Inspection # 689301178

Before:



Erosion along West side of access road

After:



Bar Ditch re-defined, rock check dams installed