

O'toole A

Before:

Inspection # 689301172

After:



Ditch erosion along side of road on east side



Ditch erosion along side of road on east side. Looking down hill



Bar ditch re-defined on east side, looking down the acc. rd from pad



Bar ditch on east side looking down hill from location.

O'toole A

Before:

Inspection # 689301172

After:



Ditch erosion along side of road on West side. Looking down hill



Bar Ditch Re-defined, rock check dams installed to slow water velocity



Ditch erosion along side of road on West side. Looking downhill



O'toole A

Before:

Inspection # 689301172

After:



Ditch erosion along side of road on east side near curve



Bar ditch re-defined/check dams in place



Ditch erosion along side of road on east side near curve



Bar ditch re-defined/check dams in place