

# Inspection Photos

06/19/2018

Operator: WIEPKING-FULLERTON ENERGY LLC -  
96340

Location ID: 433577

Inspection Doc. Number: 682503514  
Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340  
Location ID: 433577



**Photo 1:** Photo taken from the northwest end of the location, facing north. Photo shows straw wattles have been installed on the north end. Wattles do not appear to be in proper functioning conduction, or have filled with sediment.



**Photo 2:** Photo taken from the northwest end of the location, facing south. Photo shows straw wattles have been installed on the north end. Wattles do not appear to be in proper functioning conduction, or have filled with sediment.

Inspection Photos

Operator: WIEPKING-FULLERTON ENERGY LLC - 96340

Location ID: 433577



**Photo 3:** Photo taken from the west end of the location. Photo shows water bar. BMP does not appear to have been installed in accordance to good engineering practices; water bar has not been consolidated or in proper functioning conduction, and is considered a sediment source.



**Photo 4:** Continued from photo 3.

Inspection Photos

Operator: WIEPKING-FULLERTON ENERGY LLC - 96340

Location ID: 433577



**Photo 5:** Photo taken from access road, west of the location, facing south. See comments under photo 4.



**Photo 6:** Photo taken from the south end of the location, facing north. Photo shows interim area has been fenced and slope has been repaired and stabilized with straw blankets.