

Inspection Photos
Location Name: LaSalle 14-29
Location ID: 323518



Wellhead



Battery

Inspection Photos
Location Name: LaSalle 14-29
Location ID: 323518



Corrective Action: Anchor equipment ensuring anchors are engineered so the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 603.h.(2)B. Refer to the 603.h guidance document for further details.