

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2018

Submitted Date:

06/14/2018

Document Number:

689301299**FIELD INSPECTION FORM**

Loc ID 420223	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>1600 BROADWAY ST STE 2600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> <u>25</u> Number of Comments <u>2</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420217	WELL	PR	08/29/2012	GW	045-20107	McLin C7	PR
420236	WELL	PR	08/29/2012	GW	045-20112	McLin C2	PR
420279	WELL	PR	03/03/2014	GW	045-20113	McLin C3	PR
420289	WELL	PR	03/30/2012	GW	045-20117	McLin C16	PR
420291	WELL	PR	03/03/2014	GW	045-20118	McLin C5	PR
420329	WELL	PR	10/29/2012	GW	045-20130	McLin C20	PR
420331	WELL	PR	08/29/2012	GW	045-20131	McLin C13	PR
420332	WELL	PR	11/30/2013	GW	045-20132	McLin C15	PR
420333	WELL	PR	08/29/2012	GW	045-20133	McLin C24	PR
420336	WELL	DG	06/08/2016	LO	045-20135	McLin C8	DG
420338	WELL	DG	05/10/2014	LO	045-20136	McLin C17	DG
420340	WELL	PR	08/29/2012	GW	045-20138	McLin C23	PR
420341	WELL	PR	10/29/2012	GW	045-20139	McLin C19	PR
420343	WELL	PR	10/29/2012	GW	045-20140	McLin C18	PR
420344	WELL	PR	08/29/2012	GW	045-20141	McLin C22	PR
420345	WELL	PR	11/30/2013	GW	045-20142	MCLIN C6	PR

**General Comment:**[Routine Field inspection](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:	1-855-625-9922			
Corrective Action:				Date:
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Stained Rock in Battery containment, see photos			
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.			Date: 07/14/2018
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Livestock gates			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Emission Control Device	# 2			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 10			
Comment:				
Corrective Action:				Date:
Type: Flow Line	# 1			
Comment:	Water line/header			
Corrective Action:				Date:
Type: Plunger Lift	# 14			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 1			
Comment:				
Corrective Action:				Date:

Type: Ancillary equipment	# 1		
Comment:	Chemical unit at Wellhead		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,	
Comment:	Centralized Battery					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	420217	Type:	WELL	API Number:	045-20107	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	420236	Type:	WELL	API Number:	045-20112	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	420279	Type:	WELL	API Number:	045-20113	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	420289	Type:	WELL	API Number:	045-20117	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	420291	Type:	WELL	API Number:	045-20118	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	420329	Type:	WELL	API Number:	045-20130	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	420331	Type:	WELL	API Number:	045-20131	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	420332	Type:	WELL	API Number:	045-20132	Status:	PR	Insp. Status:	PR

<b>Producing Well</b>				
Comment:	Well Producing on plunger lift			
Corrective Action:		Date:		
Facility ID: 420333	Type: WELL	API Number: 045-20133	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Well Producing on plunger lift			
Corrective Action:		Date:		
Facility ID: 420336	Type: WELL	API Number: 045-20135	Status: DG	Insp. Status: DG
<b>Well Drilling</b>				
<b>Rig:</b>	Rig Name: _____	Pusher/Rig Manager: _____		
	Permit Posted: _____	Access Sign: _____		
<b>Well Control Equipment:</b>				
Pipe Ram: _____	Blind Ram: _____	Hydril Type: _____		
Pressure Test BOP: _____	Test Pressure PSI: _____	Safety Plan: _____		
<b>Drill Fluids Management:</b>				
Lined Pit: _____	Unlined Pit: _____	Closed Loop: _____	Semi-Closed Loop: _____	
Multi-Well: _____	Disposal Location: _____			
Comment:	No drill rig on location			
Corrective Action:		Date:		
Facility ID: 420338	Type: WELL	API Number: 045-20136	Status: DG	Insp. Status: DG
<b>Well Drilling</b>				
<b>Rig:</b>	Rig Name: _____	Pusher/Rig Manager: _____		
	Permit Posted: _____	Access Sign: _____		
<b>Well Control Equipment:</b>				
Pipe Ram: _____	Blind Ram: _____	Hydril Type: _____		
Pressure Test BOP: _____	Test Pressure PSI: _____	Safety Plan: _____		
<b>Drill Fluids Management:</b>				
Lined Pit: _____	Unlined Pit: _____	Closed Loop: _____	Semi-Closed Loop: _____	
Multi-Well: _____	Disposal Location: _____			
Comment:	No drill rig on location			
Corrective Action:		Date:		
Facility ID: 420340	Type: WELL	API Number: 045-20138	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Well Producing on plunger lift			
Corrective Action:		Date:		

Facility ID:	420341	Type:	WELL	API Number:	045-20139	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Well Producing on plunger lift								
Corrective Action:								Date:	
Facility ID:	420343	Type:	WELL	API Number:	045-20140	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Well Producing on plunger lift								
Corrective Action:								Date:	
Facility ID:	420344	Type:	WELL	API Number:	045-20141	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Well Producing on plunger lift								
Corrective Action:								Date:	
Facility ID:	420345	Type:	WELL	API Number:	045-20142	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Well Producing on plunger lift								
Corrective Action:								Date:	

## Environmental

### Spill/Remediation:

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment: 2 ECB's on location

Pilot: ON

Wildlife Protection Devices (fired vessels): YES



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				
Blankets						
		Ditches				
Slope Roughening						
		Gravel				

Comment: [Slope erosion behind tank battery, see photos](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 07/14/2018

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401674388	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4495109">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4495109</a>
689301300	Inspection Photo 689301300	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4495105">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4495105</a>