

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/06/2018

Submitted Date:

06/19/2018

Document Number:

689801272

FIELD INSPECTION FORM

Loc ID 313000 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10407
Name of Operator: ANTLER ENERGY LLC
Address: PO BOX 104
City: BAGGS State: WY Zip: 82321

Findings:

- 12 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	
Neidel, Kris		kris.neidel@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223250	WELL	PR	09/22/1985	OW	081-06614	PTASYNSKI 1X	PR

General Comment:

[Routine FIU follow up inspection.](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers. Only one of two tanks labeled.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/27/2017
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Horizontal Heated Separator	# 1		
Comment:	40.91533, -108.32238 ~ 18 feet between pumpjack and heated separator.		
Corrective Action:	Move equipment to comply with minimum 75 foot setback as per Rule 605.b.(4).	Date:	01/14/2016
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Vertical Heated Separator	# 1		
Comment:	40.91535, -108.32202 Stained soil around separator base.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.	Date:	07/19/2018
Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Dehydrator	# 1		

Comment:	40.91554, -108.32214		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	40.91554, -108.32214		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	HEATED STEEL AST		40.915110,-108.322270
Comment:	Stained soil at tank loadout.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 07/28/2016

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 223250 Type: WELL API Number: 081-06614 Status: PR Insp. Status: PR

Producing Well

Comment: **Pumping.**
Produced volumes are required to be reported accurately from the wellhead meter every month, and the form 7 reporting does not reflect that accurate measurement.

Corrective Action: **Please contact Teri Ikenouye (production supervisor) to discuss reporting parameters.**

Date: 07/19/2018

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)											
Oily Soil	Land Treatment	Inadequate	40.915120	-108.322340										
<table border="1" style="width: 100%;"> <tr> <td style="width: 20%;">Comment</td> <td colspan="3"></td> <td style="width: 10%;"></td> </tr> <tr> <td>Corrective Action</td> <td colspan="3"> <p style="color: red;">A previous operator opened a land treatment E&P facility in 2011. The facility was approved in Remediation project number 7362. No project updates have been received by COGCC since this project was started. By 5/28/2018, please provide a supplement eForm 27 update on project number 7362.</p> </td> <td>Date: <u>06/22/2018</u></td> </tr> </table>					Comment					Corrective Action	<p style="color: red;">A previous operator opened a land treatment E&P facility in 2011. The facility was approved in Remediation project number 7362. No project updates have been received by COGCC since this project was started. By 5/28/2018, please provide a supplement eForm 27 update on project number 7362.</p>			Date: <u>06/22/2018</u>
Comment														
Corrective Action	<p style="color: red;">A previous operator opened a land treatment E&P facility in 2011. The facility was approved in Remediation project number 7362. No project updates have been received by COGCC since this project was started. By 5/28/2018, please provide a supplement eForm 27 update on project number 7362.</p>			Date: <u>06/22/2018</u>										

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: [Pit mentioned in previous reports.](#)

Corrective Action

Date: 05/28/2018

COGCC Comments

Comment	User	Date
Follow up to inspection from 3/26/2017 document number 673404307. No corrective actions have been met.	waldrone	06/19/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401678345	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4498709
689801277	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4498706