

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 2. Risers at entrance.
6/22/2018



Photo 3. Risers at entrance.
1/3/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 4. Free fluid at tank base.
6/22/2018



Photo 5. Free fluid at tank base.
6/22/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 6. Free fluid and stained soil at tank base.
6/22/2018



Photo 7. Free fluid and stained soil at tank base.
1/3/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 8. Stained soil.
6/22/2018



Photo 9. Stained soil and debris.
6/22/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 10. Stained soil and debris.
1/3/2018



Photo 11. Stained soil.
6/22/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 12. Stained soil at tank loadouts.
6/22/2018



Photo 13. Stained soil at tank loadouts.
1/3/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 14. Stained soil at tank loadout.
6/22/2018



Photo 15. Stained soil at tank loadouts.
1/3/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



**Photo 16. Pit with gaps in netting, oil, less than
2 feet of freeboard
6/22/2018**



**Photo 17. Pit with unmarked riser.
6/22/2018**

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 18. Pit with gaps in netting, oil, less than 2 feet of freeboard.
6/22/2018



Photo 19. Stained soil on east side of pit with "flowline".
6/22/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 20. Pit with gaps in netting, oil, less than 2 feet of freeboard.
1/3/2018



Photo 21. Stained soil on east side of pit with "flowline".
1/3/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 22. No tank labels, no berm, holes in tank.
6/22/2018



Photo 23. Riser.
6/22/2018