

Inspection Photos
Location Name: Tow Creek 13-11
API: 05-107-06051



Photo 1. Overview of location taken at entrance facing southeast.



Photo 2. Stained soil at tank base.

Inspection Photos
Location Name: Tow Creek 13-11
API: 05-107-06051



Photo 3. Bucket at loadout with stained soil around base.



Photo 4. Bucket from photo 3 with fluid in it.