

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/19/2018

Submitted Date:

06/20/2018

Document Number:

679700982**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Barber, Matt		mbarber@hpres.com	
Axelson, John		john.axelson@state.co.us	
Sheila Singer		ssinger@hpres.com	
COGCC Enforcement		dnr_cogccenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454282	LAND APPLICATION SITE	AC			-	Krier #4	EI
455159	SPILL OR RELEASE	AC	06/12/2018		-	Krier #4	EI

General Comment:COGCC Environmental Inspection in response to spill discovered by Operator 6/19/2018 and reported the same day.

Inspected Facilities								
Facility ID:	454282	Type:	LAND	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	455159	Type:	SPILL OR	API Number: -	Status:	AC	Insp. Status:	EI

--

Environmental**Spill/Remediation:**

Comment: COGCC inspection of spill verbally reported by Operator to COGCC on 6/19/2018. Thunderstorm and rain on 6/18/2018 caused stormwater to breach site stormwater BMPs and carry drilling fluid offsite, following the same path as spill ID 455159. Vac truck was onsite steamcleaning at the intersection of Weld County Roads 68 & 91.

Corrective Action: Operator shall continue recovery efforts to stabilize the site and remove standing liquids in an effort to prevent further migration of drilling fluids. Discontinue hauling drilling fluid to the Krier 4 land application site until a stormwater plan is developed that is adequate to withstand severe thunderstorms and intense rain. Form 19 Initial Report is due 6/21/2018 and Form 19 Supplemental Report is due 6/28/2018.

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401679911	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4499801
679700983	Krier 4 Inspection Photos 6-19-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4499800