

Well Name : Hazel 3

API # : 067-06397



Photo 1: Wellhead sign.



Photo 2: Impacted soil pile at wellhead.

Well Name : Hazel 3

API # : 067-06397



Photo 3: Impacted soil pile at wellhead.



Photo 4: Impacted soil under motor.



Well Name : Hazel 3

API # : 067-06397



Photo 5: Sucker rod and production related debris at pump jack.



Photo 6: Anchor marker needing repair.