

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/13/2018

Submitted Date:

06/28/2018

Document Number:

688800164

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
316806 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 56680  
 Name of Operator: MERRION OIL & GAS CORP  
 Address: 610 REILLY AVENUE  
 City: FARMINGTON State: NM Zip: 87401

**Findings:**

- 11 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Joyner, Ryan		rjoyner@blm.gov	
Fischer, Alex		alex.fischer@state.co.us	
Thompson, Philana	(505) 324-5300	pthompson@merrion.bz	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107769	PIT	AC	09/23/1999		-	HAMM CANYON FEDERAL	AC
232844	WELL	PR	06/05/1980	GW	113-06033	HAMM CANYON-FEDERAL 14-26 1	EI

**General Comment:**

On June 13, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Merrion Oil and Gas Corp. Hamm Canyon Federal 14-26 #1, in coordination with the BLM. For the most recent field inspection report for this facility, please refer to document #680401071.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Tanks are labeled with contents and capacity, and have NFPA labels.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Open topped tank does not have labels or placards.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 07/27/2018
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds present near fired equipment.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Perimeter fencing around well head.		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Perimeter fencing around tank battery.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Perimeter fencing around horizontal heated separator.		
Corrective Action:			Date:

<b>Equipment:</b>		corrective date
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Dehydrator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	STEEL AST		38.120214,-108.833348
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		38.120071,-108.833046
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLs	STEEL AST		38.120169,-108.833361	
Comment:						
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No						
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**

Facility ID: 107769 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 232844 Type: WELL API Number: 113-06033 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: <u>Blowdown</u>	Lined: <u>NO</u>	Pit ID: <u>107769</u>	Lat: <u>38.120412</u>	Long: <u>-108.833075</u>
-----------------------	------------------	-----------------------	-----------------------	--------------------------

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: Operator shall submit a Form 27 to close this historic pit in the COGIS database.

Corrective Action:  Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>On June 13, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Merrion Oil and Gas Corp. Hamm Canyon Federal 14-26 #1, in coordination with the BLM. For the most recent field inspection report for this facility, please refer to document #680401071.</p> <p>During this inspection it was noted that the earthen berm around the open topped produced water vessel may need to be repaired to provide adequate capacity. The open topped tank does not have labels or an NFPA placard.</p> <p>Pit Facility ID #107769 is a historic pit with an active status in the COGIS database. The operator is coordinating with the BLM regarding this pit closure. A Form 27, required by Rule 905.b, shall be submitted by the operator to close this pit in the COGIS database.</p>	hughesj	06/27/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800165	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4509012">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4509012</a>