

Inspection Photos
Location Name: Foster State 1
API: 05-081-07821



Photo 1. Overview of location taken at entrance facing southwest.



Photo 2. No wellhead sign.

Inspection Photos
Location Name: Foster State 1
API: 05-081-07821



Photo 3. Cuttings stored on location.



Photo 4. Cuttings stored on location.

Inspection Photos
Location Name: Foster State 1
API: 05-081-07821



Photo 5. Example of overgrown section of access road.



Photo 6. Stormwater debris in road that has been moved/eaten by livestock/wildlife.

Inspection Photos
Location Name: Foster State 1
API: 05-081-07821



Photo 7. Example of rutted section of access road. Ruts 12-20" deep.



Photo 8. Example of rutted section of access road.