

Location			
Lease Road:			
Type	Main		
comment:	Main road to Booth N 25-19 (API# 05-123-25620) battery is adequate.		
Corrective ActionL		Date:	
Type	Access		
comment:	Access road to Booth N 25-19 (API# 05-123-25620) wellhead is adequate. 2-Track Ag road.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Tank Battery signs for Booth N 25-19 (API# 05-123-25620), Booth N 25-3 (API# 05-123-15479), Booth N 25-4 (API# 05-123-15478), Booth N 25-5 (API# 05-123-18082), Booth N 25-6 (API# 05-123-18083), Booth N 25-18D (API# 05-123-31511), Booth N 25-31D (API# 05-123-31514) are not posted.		
Corrective Action:	Signs and Markers Permanent Designations at Wells and Batteries. Install sign(s) to comply with Rule 210.b.		Date: 07/25/2018
Emergency Contact Number:			
Comment:	Emergency contact numbers at battery for Booth N 25-19 (API# 05-123-25620), Booth N 25-3 (API# 05-123-15479), Booth N 25-4 (API# 05-123-15478), Booth N 25-5 (API# 05-123-18082), Booth N 25-6 (API# 05-123-18083), Booth N 25-18D (API# 05-123-31511), Booth N 25-31D (API# 05-123-31514) are not posted.		
Corrective Action:	Signs and Markers Permanent Designations at Wells and Batteries. Install sign(s) to comply with Rule 210.b.		Date: 07/25/2018
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Booth N 25-19 (API# 05-123-25620) has iron panel fencing.		
Corrective Action:		Date:	
Equipment:			
Type: Emission Control Device	# 2		corrective date
Comment:	South ECD: Controls separator VOCs. North ECD: Controls oil tanks VOCs.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:	Separator has 7 commingled wells. 1.) Booth N 25-19 (API# 05-123-25620) 2.) Booth N 25-3 (API# 05-123-15479) 3.) Booth N 25-4 (API# 05-123-15478) 4.) Booth N 25-5 (API# 05-123-18082) 5.) Booth N 25-6 (API# 05-123-18083) 6.) Booth N 25-18D (API# 05-123-31511) 7.) Booth N 25-31D (API# 05-123-31514)		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Methanol drum (55 gal.), pump, & spill tray at separator.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	This centralized battery serves 5 locations (309939, 328050, 328051, 329951, 329952).				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.377560,-104.848010
Comment:					
Corrective Action:			Date:		

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Produced oil tanks shares berms with produced H2O vaults.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Produced H2O vaults shares berms with produced oil tanks.				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 275034 Type: WELL API Number: 123-25620 Status: PR Insp. Status: PR

Producing Well

Comment: PR.

Corrective Action:

Date:

BradenHead

Comment: Bradenhead appears to be plumbed to surface.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Did not inspect the following 6 wells at this time: 1.) Booth N 25-3 (API# 05-123-15479) 2.) Booth N 25-4 (API# 05-123-15478) 3.) Booth N 25-5 (API# 05-123-18082) 4.) Booth N 25-6 (API# 05-123-18083) 5.) Booth N 25-18D (API# 05-123-31511) 6.) Booth N 25-31D (API# 05-123-31514)	evinsb	06/22/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401683637	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4503349
691200215	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4503348