

Inspection Photos
Location Name: Foundation API 045-06153
6/19/2018



Poly tank/pit looking south



Looking NE , note staining below discharge pipe



Separator pit looking N.



Separator and active pit looking N