

Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 06/27/2018



Photo 1 – Center-North area of land application area, looking west.



Photo 2 – Center-North Area of land application area, looking south.



Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 06/27/2018



Photo 3 – Northwest corner of land application area, looking east.



Photo 4 – Northwest corner of land application area, looking south.



Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 06/27/2018



Photo 5 – Area of berm breach and stormwater runoff onto State Land Board property to west.



Photo 6 – View of storm water breach and runoff onto State Land Board property to west.



Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 06/27/2018



Photo 7 Southwest corner of land application area, looking south.



Photo 8 – Southwest corner of land application area looking southeast.



Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 06/27/2018



Photo 9– Southwest corner of land application area looking east along south property boundary.



Photo 10 – View of storm water breach and runoff onto private property to south.



Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 06/27/2018



Photo 11 – Viewing west along the south property line of land application area. Area of stormwater runoff in middle of photo.



Photo 12 – View of standing stormwater in center of property.

