

**Inspection Photo
Robinson C8
API # 045-17107
Inspection # 689301421**



Location Photo #1



Location Photo #2, weeds near the wellheads

**Inspection Photo
Robinson C8
API # 045-17107
Inspection # 689301421**



Location Photo #3, weeds near the wellhead



Location Photo #4, Stained rock in battery containment

**Inspection Photo
Robinson C8
API # 045-17107
Inspection # 689301421**



Location Photo #5, Stained rock in battery containment



Location Photo #6, Stained rock in battery containment

**Inspection Photo
Robinson C8
API # 045-17107
Inspection # 689301421**



Location Photo #7, Stained rock in battery containment



Location Photo #8, Stained rock in battery containment

**Inspection Photo
Robinson C8
API # 045-17107
Inspection # 689301421**



Location Photo #9, Stained rock in battery containment



Location Photo #10, Tank sign non legible

**Inspection Photo
Robinson C8
API # 045-17107
Inspection # 689301421**



Location Photo #11, Robinson C-5



Location Photo #12, Robinson C-5