

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/18/2018

Submitted Date:

06/25/2018

Document Number:

689801281**FIELD INSPECTION FORM**
 Loc ID 451937 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------------|-------|--|---------------------------------|
| Inspections, General | | sandridgeenvironmental@sandridgeenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|----------------|-------------|
| 451937 | LOCATION | AC | 08/30/2017 | | - | Shiras CTB S11 | AO |

General Comment:[Routine FIU inspection.](#)

LocationOverall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | No label on diesel tank next to generator. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 07/25/2018 |
| Type | BATTERY | | |
| Comment: | Sign not posted or information inaccurate at well(s) or battery. No battery sign on location. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 07/25/2018 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers. 4 tanks labeled as Produced Water but contain NFPA diamond for Crude Oil. 3 tanks do not contain NFPA diamonds. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 07/25/2018 |

Emergency Contact Number:

Comment: Only emergency contact information is spray painted on tanks.

Corrective Action: Install sign to comply with Rule 210.

Date: 07/25/2018

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | 40.59723, -106.345636 | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | 40.59723, -106.345636 | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | 40.59713, -106.45766 | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |

| | | | | |
|-----------------------|-----------------------------------|--|-------|--|
| Comment: | 40.59728, -106.45746 | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Flare | # 2 | | | |
| Comment: | Combustors. 40.59723, -106.345636 | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Dehydrator | # 1 | | | |
| Comment: | 40.59723, -106.345636 | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Bird Protectors | # | | | |
| Comment: | | | Date: | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| | 7 | 500 BBLs | STEEL AST | | 40.597170,-106.456830 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | | | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|-----------------------------------|-------|----------|-------------|---|---------|----|---------------|----|
| Facility ID: | 451937 | Type: | LOCATION | API Number: | - | Status: | AC | Insp. Status: | AO |
| Producing Well | | | | | | | | | |
| Comment: | Production facility for 057-06602 | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Fail | | | | | |

Comment: [Diesel tank stored on location next to generator. Berm is built out of sand.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 07/25/2018

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401684902 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4504669 |
| 689801284 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4504661 |