

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/02/2018

Submitted Date:

07/02/2018

Document Number:

680303457**FIELD INSPECTION FORM**
 Loc ID 312276 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 72553Name of Operator: PUCKETT ENERGY COAddress: 5460 S QUEBEC STCity: GREENWOOD VLG State: CO Zip: 80111-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,	(303) 773-1094	louis@puckettcompanies.com	Inspections
Koehler, Bob		bob.koehler@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Quint, Craig		craig.quint@state.co.us	

General Comment:

UIC/MIT (5yr.) Last MIT 7/31/2013 - Well did not hold pressure - FAILED - SHUT IN WELL IMMEDIATELY until MIT passes. Reschedule MIT after repairs, pre-load and test before scheduling follow-up UIC/MIT.

Form 42 not received by Field Inspector, Operator representative stated that a Form 42 had been faxed in late June, 2018. Field Inspector accepted the test/date considering the lack of Form 42 based on the statement of the Operator rep.

NOTE TO OPERATOR:

Contact COGCC Engineering Group (Diana Burn) for directives.

Location

Lease Road:			
Type	Access		
comment:	Lease road is heavily rutted and requires filling ruts and grading. This repair and maintenance includes the areas around the battery, pits, pumpjack and wellheads.		
Corrective Action:	Repair and maintain lease road per Rule 600 series.	Date:	08/02/2018

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Satisfactory

Corrective Action: _____ Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail	Other	Fail			

Comment: [Traveled surface exhibits stormwater erosion and heavily rutted on lease road, areas around battery, pits, pumpjack and wellheads.](#)

Corrective Action: [Repair, fill ruts, grade and maintain traveled surface. Implement BMP's.](#)

Date: 08/02/2018

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
UIC/MIT FAILED - Lease road and traveled areas require repair and maintenance including stormwater BMP's.	schureky	07/02/2018