

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/19/2018

Submitted Date:

06/26/2018

Document Number:

685304920**FIELD INSPECTION FORM**Loc ID 325547 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 35720Name of Operator: GREER* JAMES R & NATALIEAddress: 7882 CO RD 100City: HESPERUS State: CO Zip: 81326**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Burger, Craig		craig.burger@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214982	WELL	DM	01/07/1987	GW	067-06587	KENNEDY 1	DM

General Comment:

Inspection completed as routine inspection requirement.

This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.

See link at end of report for path to downloadable video and pictures.

Location				
Lease Road:				
Type	Access			
comment:	Dirt two track road.			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	No wellhead sign at location. Similiar issue noted in previous inspection 685300614.			
Corrective Action:	Install sign to comply with Rule 210.b.		Date:	07/16/2018
Emergency Contact Number:				
Comment:	No contact information posted at wellhead. Similiar issue noted in previous inspection 685300614.			
Corrective Action:	Install sign to comply with Rule 210.b.			Date: 07/13/2018
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	Fluids in wellhead cellar. Similiar issue noted in previous inspection 685300614.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.			Date: 07/13/2018
In Containment: No				
Comment:	Release in unlined wellhead cellar.			
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Steel post and hog wire fencing.			
Corrective Action:			Date:	
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	Wellhead. Well appears to possibly have a below grade leak with fluids and gas migrating to the surface around wellhead.			
Corrective Action:	Excavate around wellhead to determine source of leak per Rule 605.d. "Identify and repair to comply with Rules 605.d. Contact inspection staff if bradenhead access is found and schedule a witnessed BH test using COGCC Bradenhead Testing and Reporting Procedure.			Date: 07/13/2018
Type: Flow Line	# 5			
Comment:	In use - 3" steel line from wellhead into ground. (b) point unknown (possibly connected to 6" riser below grade). Valve open. In use - 6" steel riser (possible gas dryer) at wellhead has 1" supply line off 6" riser that passes through regulator and is split into (2) 1" lines that go into ground. Valve on supply line and valves on both 1" lines. All valves open. Unused - 1" steel riser at wellhead. (B) point unknown (possible blow down for 6" riser). Open ended with valve that is currently closed.			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	YES		
Comment:	Visible gas release (bubbling) through fluids in wellhead cellar.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities									
Facility ID:	214982	Type:	WELL	API Number:	067-06587	Status:	DM	Insp. Status:	DM

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Location is surrounded by agricultural grazing/pasture land.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At the time of inspection the wellhead cellar had standing fluid surrounding wellhead and bubbles streaming to the surface around wellhead casing and in several places inside cellar area. Unknown volume. Similiar issues were identified in previous inspection 685300614.	stjohnw	06/25/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401686003	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4505871
685304947	wellhead video.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4505872
685304948	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4505873