



**Photo 1. View of the project area from the northwestern corner facing center.**



Photo 2. View of the western portion of the project area from the northwestern corner facing southward. Revegetation is progressing and comprised of grasses and shrubs such as intermediate wheatgrass (*Thinopyron intermedium*), crested wheatgrass (*Agropyron cristatum*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



**Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward.**



**Photo 4. View of dirty rags along the edge of the working area.**



**Photo 5. View erosional channel approximately 2.5 feet wide and deep in the northern portion of the project area. Stormwater controls are needed to stabilize erosion here.**



**Photo 6. View of another erosional channel approximately 2 feet wide and deep in the northern portion of the project area. Stormwater controls are needed to stabilize erosion here.**



**Photo 7. View of musk thistle (*Carduus nutans*) and Russian knapweed (*Rhaponticum repens*) within the northern interim reclamation area.**



**Photo 8. View of lush musk thistles within the northeastern portion of the project area.**