

Inspection Photos

Location Name: Roan Creek Evaporation Pit

Location ID: #391314 / Pit Facility ID #116525

Inspection Date: June 20, 2018



Photo #1 – Facility sign and gate located at SW corner entrance.



Photo #2 – Gravel stockpiles remaining outside of fenced area.



Inspection Photos

Location Name: Roan Creek Evaporation Pit

Location ID: #391314 / Pit Facility ID #116525

Inspection Date: June 20, 2018



**Photo #3 – Site-wide, uncontrolled weeds along fence line.
Photo taken at SW corner of pit.**



**Photo #4 – View from SW corner of pit, looking north. Note
sediment and salt remain on top of pit liner and weeds are
encroaching along pit perimeter.**



Inspection Photos

Location Name: Roan Creek Evaporation Pit

Location ID: #391314 / Pit Facility ID #116525

Inspection Date: June 20, 2018



Photo #5 – Torn liner at SW corner of pit, below inlet from produced water tank.



Photo #6 – Weeds and sediment transport encroaching on pit liner (west berm).



Inspection Photos

Location Name: Roan Creek Evaporation Pit

Location ID: #391314 / Pit Facility ID #116525

Inspection Date: June 20, 2018



Photo #7 – Erosion on top of west berm.



Photo #8 – Berm erosion with off-site sediment transport around pit perimeter (west berm).



Inspection Photos

Location Name: Roan Creek Evaporation Pit

Location ID: #391314 / Pit Facility ID #116525

Inspection Date: June 20, 2018



Photo #9 – Pit liner remains compromised at NE corner, as first indicated in December 19, 2017 Field Inspection Report #689100109.



Photo #10 – Evidence of erosion and sediment transport at leak detection system cover on north side of pit



Inspection Photos

Location Name: Roan Creek Evaporation Pit

Location ID: #391314 / Pit Facility ID #116525

Inspection Date: June 20, 2018



Photo #11 – More berm erosion and off-site sediment transport along north berm.



Photo #12 – Weeds growing in compromised liner area at NE corner of pit.



Inspection Photos

Location Name: Roan Creek Evaporation Pit

Location ID: #391314 / Pit Facility ID #116525

Inspection Date: June 20, 2018



Photo #13 – 300 bbl produced water AST in lined earthen berm at SW corner of pit.



Photo #14 – Overview of facility from NW.

