

Well Name : Marquez A 1  
API # : 007-06165



Photo 1: Wellhead sign.



Photo 2: Impacted soil and gravel at rear of pump jack.

Well Name : Marquez A 1  
API # : 007-06165



Photo 3: Impacted soil and gravel at exhaust outlet.



Photo 4: Impacted soil and gravel at lube oil tank spill prevention.

Well Name : Marquez A 1  
API # : 007-06165



Photo 5: Erosion channel developing at front of rock run down.



Photo 6: Vehicle frame on S perimeter.