



Photo 1. View of the project area from the southwestern corner facing eastward. Southern cut-slope does not appear stabilized as a result of undercutting at the top of the slope and sediment deposition at the toe of the slope. Stormwater controls need to be installed to stabilize erosion on the southern cut-slope



Photo 2. View of the northern portion of the project area from the northern edge facing eastward. Revegetation is progressing with shrubs and grasses such as rubber rabbitbrush (*Chrysothamnus nauseosus*) and smooth brome (*Bromus inermis*).



Photo 3. View of metal and cement debris near the well head.



Photo 4. View of unused tanks stored in the southern portion of the project area.



Photo 5. View of unused equipment in the northeastern portion of the project area.



Photo 6. View of orange fencing debris in the western portion of the project area.